MEMORANDUM

TO: Tom Harmer, Town Manager

FROM: Isaac Brownman, Public Works Director

DATE: February 11, 2019

SUBJECT: Bayfront Park Recreation Center Planning Update

Recommended Action

None, informational only.

Background

The Town Recreation Center was donated to the Town by the late Dr. Murf Klauber and transported to its current location at Bayfront Park in 1984. It is used for private event rentals, fitness classes, and Town events. In 2012, a comparative analysis was performed to determine whether it would be in the Town's best interest to renovate the existing facility or plan for the construction of a new facility. The study concluded that a new facility would be the better option. Attached is their report and below is a summary:

"WJA performed a due diligence review of the existing center including American with Disabilities Act, mechanical, electrical, plumbing, structural general maintenance conditions and operational review.

The building is approximately 30-40 years old and was relocated to this site. It was not designed to meet the current codes or wind zone requirements. Some improvements have been made to update the building but significant improvements would be required to bring the building into compliance. Due to the saltwater coastal location and general age of the existing building it has significant maintenance needs. The range of potential cost is between \$125,000 and \$150,000 (bare minimum).

Regarding operations, the proposed new community center would accommodate all existing programs. If the existing building was to remain open after the new building is complete it would require additional staff to operate, supervise, and maintain.

In conclusion there is no monetary, operational, or program benefit provided by the existing building. The capital improvements needed for long term utilization and the ongoing operational cost to the Town of Longboat Key exceed any value offered by the existing building. We therefore advise that the building should be demolished once a proposed Community Center is complete."

The Fiscal Year 2019 Budget includes funding for additional planning for the Bayfront Park Recreation Center replacement. Wannemacher Jensen Architects ("WJA") was hired to continue and refine work already produced in relation to the recreation center. WJA is also the firm who designed the recently completed renovations to Bayfront Park.

The scope of WJA work includes updating the building program and associated square footage, producing a refined floor plan based on the program, reviewing site location

options, providing recommendations, and also a preliminary opinion of probable cost based on the refined building program.

Three (3) refined floor plans and site locations are attached for reference. Staff preference is Scheme "A."

Next Steps

- 1. WJA provide a 3-Dimensional Computer model to illustrate the design intent of the preferred option.
- 2. WJA develop a preliminary range of probable construction cost
- 3. Prepare a final presentation floor plan, site plan, and color rendering

It is anticipated that these steps can be completed within the next 45-days. At this time, the construction of a new facility is not currently funded in the Town's five (5) year capital plan.

Attachments

WJA – Bayfront Park Recreation Center Floor Plan and Site Layouts
WJA – Bayfront Park Community Center Existing Building Due Diligence Assessment
Report




BAYFRONT PARK RECREATION CENTER PLANNING


Town Commission Regular Workshop February 19, 2019




SCHEME - A













SCHEME A - EXISTING REC CENTER LOCATION







Maintains existing park views and ambiance



SCHEME - B









SCHEME - B MULTIPURPOSE 426 SF STO 177 SF 88 88 PATIO 495 SF KITCHEN 370 SF MULTIPURPOSE RM 3001 SF



SCHEME - B - RELOCATE ROADWAY











SCHEME - C SCHEME - C -8793 SF -EXISTING RECREATION CENTER CAN REMAIN OPEN DURING CONSTRUCTION -MINIMAL IMPACT TO EXISTING PARK **GULF OF MEXICO** SARASOTA BAY 000 \$\$\$\$\$ &











SCHEME - C - EXISTING STORM WATER AREA











BAYFRONT PARK RECREATION CENTER PLANNING

Public Works Staff recommends Scheme A

Next Steps

- 1. WJA provide a 3-Dimensional Computer model to illustrate the design intent of the preferred option.
- 2. WJA develop a preliminary range of probable construction cost
- 3. Prepare a final presentation floor plan, site plan, and color rendering

It is anticipated that these steps can be completed within the next 45-days.

Bayfront Park Community Center

Town of Longboat Key

Existing Building Due Diligence Assessment Report





Summary:

WJA performed a due diligence review of the existing center including American with Disabilities Act, mechanical, electrical, plumbing, structural general maintenance conditions and operational review.

The building is approximately 30-40 years old and was relocated to this site. It was not designed to meet the current codes or wind zone requirements. Some improvements have been made to update the building but significant improvements would be required to bring the building into compliance. Due to the saltwater coastal location and general age the existing building it has significant maintenance needs. The range of potential cost is between \$125,000 and \$150,000.

Regarding operations, the proposed new community center would accommodate all existing programs. If the existing building was to remain open after the new building is complete it would require additional staff to operate, supervise, and maintain.

In conclusion there is no monetary, operational, or program benefit provided by the existing building. The capital improvements needed for long term utilization and the ongoing operational cost to the Town of Longboat Key exceed any value offered by the existing building. We therefore advise that the building should be demolished once a proposed Community Center is complete.

Photo Documentation:

The following images were taken during our due diligence inspection. They depict various observations, deficiencies and code violations within the existing structure.





ADA violation – no railing extension



ADA violation – no railing extension

ADA – Americans with Disabilities Act **FBC** – Florida Building Code



FBC Code Violation – Open tread stairs are not allowed in commercial construction.



Guard rail height varies from 41-43 inches. 42" guardrail is required per FBC





ADA Violation - Ramp run is greater than 30'-0"



ADA Violation Railing - heights vary, no 1-1/2" continuous railing is provided. The ramp also displays a overall level of disrepair reducing functionality.



Plumbing is below flood plain without visible back flow preventer



Railing should not allow a sphere greater than 4" to pass between railings. This is a liability for youth patrons.





General ramp disrepair



The Gutter is detached or bent at various locations



General ramp disrepair



Exterior paint is pealing exposing wood siding, fascia, and sheathing





Exposed wiring at removed fixture



Exterior electrical fixtures do not appear to be ground fault protected. Potential liability



Paint delamination



Existing glazing does not meet hurricane impact rating requirements.





Valves and fire riser are exposed rusting





Condensers appear to be functional and have usable life available.







Lateral bracing is very loose and would be ineffective in a storm situation.



2x8 framing utilized for floor joist. 2x10min is recommended



Lateral bracing is rusting through at multiple locations



2x8 framing utilized for floor joist.2x10 min is recommended for Assembly structures





Extensive use of rubber couplings



Exposed infrastructure above Art Studio Space



Extensive use of rubber couplings



Exposed infrastructure above Art Studio Space





Requires proper hurricane straps and tie down



Requires proper hurricane straps and tie down



Building is sprinkled. WJA does not recommend exposed pipe in salt water locations




Exposed Wiring.





Rusting electrical conduit



Toilet room below flood plain



ADA requires 12" at push side of door jamb




Ceiling/leak repair





Non functional door closer





The toilet is not the correct distance from the wall per ADA




The first level sinks are acceptable per ADA





The building does not have code required ducted return air and does not meet the current outside air requirements



The current electrical system is at full capacity



The building does not have adequate storage



Fire alarm system is up to date






Flexible duct lengths exceed FBC requirements



Openings not sealed between ceiling and attic



Art Studio is below grade and requires sump pump



Art Studio is below grade and requires sump pump





Openings not sealed between ceiling and attic



Air transfer grill to office should be ducted



Inefficient insulation at ceiling. No insulation at roof deck



Existing drain leak





VCT is in disrepair. WJA does not recommend VCT due to the ongoing maintenance required



Windows/glazing does not meet current wind zone requirements



No Acoustic separation between office and program room



Wall paper is peeling and aesthetically dated.





Toilet room does not meet ADA min dimensions



Piping is not protected per ADA



Toilet room does not meet ADA min dimensions



Toilet dimension does not meet min ADA dimension requirements





Door handle should be a lever per ADA. Push side of the door should have 12" clear



Non compliant ADA toilet



Piping is not protected per ADA



Fixtures should be lever controlled







Triple bowl sink is required Separate hand sink is required



Existing Center Lacks appropriate accessible storage in all spaces







A2.0

Bayfront Park Recreation Center Ground Floor Plan - Scheme A 01-16-2019

Wannemacher Jensen Architects, I 180 Mirrot Lake Drive North St. Petersburg, Florida 33701-3214 (727) 822-5568 fax (727) 822-5475 www.wjarches

©Wannemacher Jensen Architects, Inc.






A2.1

Bayfront Park Recreation Center First Floor Plan - Scheme A 01-16-2019

Wannemacher Jensen Architects, In 180 Mirrot Lake Drive North St. Petersburg, Florida 33701-3214 (727) 822-5566 fax (727) 822-5475 www.wijar.com


©Wannemacher Jensen Architects, Inc











B2.0

Bayfront Park Recreation Center Ground Floor Plan - Scheme B 01-16-2019

Wannemacher Jensen Architects, In 180 Mirro Lake Drive North St. Petersburg, Florida 33701-3214 (727) 822-5666 fax (727) 822-5475 www.wijar.com








B2.1

Bayfront Park Recreation Center First Floor Plan - Scheme B 01-16-2019 Wannemacher Jensen Archit 180 Mirror Lake Drive North St. Petersburg, Florida 33701-3214 (727) 822-5566 fax (727) 822-5475 www.wiarc.com

©Wannemacher Jensen Architects, Inc.








Bayfront Park Recreation Center Site Plan - Scheme C 01-16-2019






C2.0

Bayfront Park Recreation Center First Floor Plan - Scheme C 01-16-2019

Wannemacher Jensen Architects, I 180 Miror Lake Drive North St. Petersburg, Florida 33701-3214 (729) 822-5566 | fax (727) 822-5475 www.wjgr.com

©Wannemacher Jensen Architects, Inc.





C2.1

Bayfront Park Recreation Center First Floor Plan - Scheme C 01-16-2019

Wannemacher Jensen Architects, Inc. 180 Mirrot Lake Drive North St. Pelersburg, Florda 33701-3214 (727) 822-5566 fax (727) 822-5475 www.wigar.com

©Wannemacher Jensen Architects, In





End of Agenda Item