

From: [Charlie Mopps](#)
To: [EDDIE ABRAMS](#)
Cc: [Isaac Brownman](#); [Kalee Shaberts](#)
Subject: RE: 7025 Longboat Dr. north
Date: Thursday, August 15, 2024 7:09:23 AM

Eddie, thanks for the response. Due to the height of the tides the pumps would had been ineffective. They would have been pumping water back on themselves.

Very Respectfully,

Charles “Charlie” Mopps, PMP

Program Manager/Assistant Public Works Director | Town of Longboat Key Public Works

From: EDDIE ABRAMS <asoccered@aol.com>
Sent: Wednesday, August 14, 2024 6:27 PM
To: Charlie Mopps <cmopps@longboatkey.org>
Subject: 7025 Longboat Dr. north

CAUTION: This Message Is From an External Sender

Exercise caution when opening attachments or clicking links, especially from unknown senders.

[Report Suspicious](#)

Charlie

These were taken around my house and my sons house at 7049 . These were taken before and after the worst . We did not have water in our living part but it came close, hope these help.

Also, why were there NO pumps in place? You mentioned that the town was getting some pumps to help the situation. Just wondering.

Thanks















Sent from my iPhone