



- LEGEND
- ◁ = REDUCER
  - ⊗ = GATE VALVE
  - ⊕ = FIRE HYDRANT
  - ⊥ = WATER STUB OUT

1) NOTE: INTERIOR IMPROVEMENTS ARE NOT LOCATED EXCEPT AS NOTED

2) ELEVATIONS ARE BASED ON NATIONAL GEODETIC SURVEY MONUMENT #60 (ELEVATION 7.05')

3) BASE LINE BASED ON MONUMENTED DATUM LINE.

4) SOME OF THE UNDERGROUND LOC'S WERE BASED ON INFORMATION SUPPLIED BY CONTRACTOR

**ASBUILT SURVEY**  
 OF  
**WATER SERVICE**  
 FOR  
**CEDARS EAST**  
**CONDOMINIUM**  
 IN  
**SEC. 26, TWP. 35 S. RGE. 16 EAST**  
 FOR: W.G. MILLS INC.

I HEREBY CERTIFY THAT THE AS-BUILT OF THE UTILITIES SHOWN, SUPERIMPOSED UPON THE DESIGN CONSTRUCTION PLANS IS A TRUE AND CORRECT REPRESENTATION OF THE IMPROVEMENTS AS SHOWN.

ZOLLER, NAJJAR & SHROYER, INC. *L.E. Mercer*  
 P.O. Box 9448  
 Bradenton, Florida 33506 L.E. MERCER #1324

REVISIONS	
1	11-19-86 3:57 PM
2	2:54 PM W.G. MILLS
3	
4	
5	
6	
7	

**Zoller, Najjar & Shroyer, Inc.**  
 Engineers, Planners, Surveyors & Landscape Architects

201 5th Avenue Drive East  
 Post Office Box 9448  
 Bradenton, Florida 33506  
 Telephone (813) 748-8080

DESIGNED \_\_\_\_\_ CHECKED *W* DATE *11/10/86* SCALE *1"=40'*  
 DRAWN *BS* COMP \_\_\_\_\_ JOB NO. *00-7729* FILE NO. \_\_\_\_\_ SHEET *2* OF *4*