



- LEGEND
- = LIFT STATION
  - = MANHOLE
  - = SANITARY STUBS
- 1) NOTE: INTERIOR IMPROVEMENTS ARE NOT LOCATED EXCEPT AS NOTED
- 2) ELEVATIONS ARE BASED ON NATIONAL GEODETIC SURVEY MONUMENT #60 (ELEVATION 7.05')
- 3) BASE LINE BASED ON MONUMENTED DATUM LINE
- 4) SOME OF THE UNDERGROUND LOC.'S WERE BASED ON INFORMATION SUPPLIED BY CONTRACTOR

**AS BUILT SURVEY  
OF  
SANITARY SEWER  
FOR  
CEDARS EAST  
CONDOMINIUM  
IN  
SEC. 26, TWP. 35 S. RGE. 16 EAST**

FOR: W.G. MILLS INC.

I HEREBY CERTIFY THAT THE AS-BUILT OF THE UTILITIES SHOWN, SUPERIMPOSED UPON THE DESIGN CONSTRUCTION PLANS IS A TRUE AND CORRECT REPRESENTATION OF THE IMPROVEMENTS AS SHOWN.

ZOLLER, NAJJAR & SHROYER, INC. *L.E. Merler*  
P.O. Box 9448  
Bradenton, Florida 33506 L.E. MERLER #1324

REVISIONS	
1	
2	
3	
4	
5	
6	
7	

**Zoller, Najjar & Shroyer, Inc.**  
Engineers, Planners, Surveyors & Landscape Architects

201 3th AVENUE DRIVE EAST  
POST OFFICE BOX 9448  
BRADENTON, FLORIDA 33506  
TELEPHONE (813) 748-8080

DESIGNED \_\_\_\_\_ CHECKED *ME BC* DATE *11/10/86* SCALE *1"=40'*  
DRAWN *ME* COMP \_\_\_\_\_ JOB NO. *00-7729* FILE NO. \_\_\_\_\_ SHEET *3* OF *4*